

10/664102 cof c

Docket No.: MERMIS 3.0-004

(PATENT)

## IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Letters Patent of: Webber et al.

Patent No.: 7,031,485

Issued: April 18, 2006

For: EAR MOUNTING ASSEMBLY FOR ELECTRONIC COMPONENT

Certificate of Correction Branch Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

Certificate JUN 0 1 2006

of Correction

## REQUEST FOR CERTIFICATE OF CORRECTION PURSUANT TO 37 CFR 1.323

Dear Sir:

Enclosed herewith is a Certificate of Correction with respect to the above-identified U.S. Patent. You are hereby authorized to charge Deposit Account No. 12-1095 in the amount of \$100 to cover the required fee for filing a Certificate of Correction under § 1.323.

These errors were inadvertent, occurred in good faith and do not involve any changes which constitute new matter.

We look forward to early return of the Certificate of Correction duly certified.

Dated: May 25, 2006

Respectfull submitted

Orville R. Cockings

Registration No.: 42,424 LERMER, DAVID, LITTENBERG,

KRUMHOLZ & MENTLIK, LLP

600 South Avenue West

Westfield, New Jersey 07090

(908) 654-5000

Attorney for Applicant

660465\_1.DOC

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number. (Also Form PTO-1050)

# UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

Page \_1\_ of \_1\_

PATENT NO.

7,031,485

APPLICATION NO.

10/664,102

**ISSUE DATE** 

April 18, 2006

INVENTOR(S)

Meridyth Mischel Webber and Lawrence R. Stotts

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

#### Column 4

Line 38, "T" should be deleted;

#### Column 9

Line 11, "members" should read --member--;

#### Column 10

Line 13 "head set" should read --headset --;

## Column 10

Line 13 "head set" should read --headset--;

Line 27, "wherein housing" should read --wherein said housing --; Line 31, "wherein housing" should read --wherein said housing--;

MAILING ADDRESS OF SENDER (Please do not use customer number below): Orville R. Cockings LERNER, DAVID, LITTENBERG, KRUMHOLZ & MENTLIK, LLP 600 South Avenue West Westfield, New Jersey 07090

# UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

Page \_1\_ of \_1

PATENT NO.

7,031,485

APPLICATION NO.

10/664,102

**ISSUE DATE** 

April 18, 2006

INVENTOR(S)

Meridyth Mischel Webber and Lawrence R. Stotts

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

## Column 4

Line 38, "T" should be deleted;

#### Column 9

Line 11, "members" should read --member--;

### Column 10

Line 13 "head set" should read --headset --;

### Column 10

Line 13 "head set" should read --headset--;

Line 27, "wherein housing" should read --wherein said housing --;

Line 31, "wherein housing" should read -wherein said housing--;

MAILING ADDRESS OF SENDER (Please do not use customer number below): Orville R. Cockings LERNER, DAVID, LITTENBERG, KRUMHOLZ & MENTLIK, LLP 600 South Avenue West Westfield, New Jersey 07090